

APPENDIX B: Bridlington School - Accessibility Plan

Area of School	Description	Issues arising	Proposed Resolution
Reception / Astro Centre	Single storey building Accessible toilet Accessible shower room	None	N/A
Sport Hall	Single storey building Two accessible toilets	None	N/A
English Block	Single storey building Boys accessible toilet	No accessible toilet in the staff or girls' toilets (no current need for this provision – to be reviewed as necessary). The path around the block is quite narrow for wheelchair use. All external markings denoting changes in height need refreshing. There is a slight height difference between the new path and the entrance door.	The nearest accessible toilet is in the Performing Arts block. New entrance path provides alternative means of access for wheelchair users. Lines to be re-painted. Site team made aware.
Performing Arts Block	Two storey building Passenger lift Accessible toilet on each floor Refuge Point with Evacuation Aid	None	N/A
Main Building – ground floor	Accessible Toilet Accessible Shower room	There is a small difference in height between the edge of the courtyard and the entrances to the link corridor and to the entrance to Y11 area. All external markings denoting changes in height need refreshing	Site team made aware. To be repainted.

Area of School	Description	Issues arising	Proposed Resolution
Main building – ground floor Assembly Hall	Currently used as dining area for students	Side stairs from main hall floor to raised walkway now in regular use. Lines require demarcation – one set has been done, but not the other.	Request additional floor tape to show changes in height.
Main Building – first floor (IT Rooms and Support Services)	First floor location Access via passenger lift in Performing Arts Stairlift up to IT rooms Refuge Point with Evacuation Aid	Access to the nearest disabled toilet from support services is in Performing Arts which is a short distance away but requires the use of the stair lift, which can be time consuming.	Could consider adding a disabled toilet into the sixth form boys & girls toilets if necessary, but would still require the use of the stair lift from the IT Rooms.
Maths, History & Languages Block	Two Storey building Accessible toilet on each floor Passenger lift Refuge point with evacuation aid	None	N/A
ADT Block	Single Storey Building	No accessible toilet. All external markings denoting changes in height need refreshing.	Nearest accessible toilet is on the admin corridor in the main block. Lines to be repainted.
Science, Geography & Religious Studies Block	Two storey building Passenger lift Refuge point with evacuation aid Accessible toilet on first floor	No accessible toilet on the ground floor All external markings denoting changes in height need refreshing	Nearest accessible toilet is on the admin corridor, in the main building Lines to be repainted.
Pavilion (POD)	Single storey building Accessible toilet	None	N/A
Gym	Single storey building Accessible entrance on the side of the building	No accessible toilet All external markings denoting changes in height need refreshing	Nearest accessible toilet is in the Pavilion. Lines to be repainted.

Area of School	Description	Issues arising	Proposed Resolution
Harland House	Two storey building	No entrance for wheelchair users No accessible toilet No stair lift	The original building was intended for domestic use and so does not include any accessible features. Quotes obtained to add accessible entrances and an extension for a disabled toilet are cost prohibitive, but must be possible with external funding.
External Areas	Netball Courts	Cannot be accessed by wheelchair users due to access via stairs. The yellow painted lines on the stairs to the netball courts are faded from use.	Activity unlikely to be undertaken by wheelchair users, but subject to review. Lines to be re-painted.
External Areas	Area between ADT and gym	Uneven ground resulting from removal of tree a number of years ago. The area surrounding the tree was filled with pebbles, but these have disappeared over a number of years.	Referred to the site team for recommendations. Ideally to be made good in line with the surrounding area.
External Areas	Walkway between Gym & Science block	Stairs are marked to show changes in height, but the side of the path is not	Lines to be added.
External Areas	Driveway leading to St Johns Avenue entrance	Hazard lines on speed bumps have faded.	Lines to be repainted.

APPENDIX B: Bridlington School - Accessibility Plan continued ...

	Area	Location of Stairs	Notes
Markings for changes in height for visually impaired students	Astro Centre	None	N/A
	Sports Hall	None	N/A
	English Block	External steps at front of block	Lines in place, need refreshing.
	Performing Arts	Stairs at each entrance to the block	Stairs have light vinyl with dark edge.
	Main Building – IT	Stairs up to IT2	Stairs have dark carpet with light edge.
		Stairs near Headteacher’s office	Stairs have dark carpet with light edge.
	Main Building – Support Services	Stairs up to Support Services	Stairs have dark carpet with light edge.
	Maths, History and Languages	Stairs at each end of the block	Stairs have light vinyl tread with black edge.
	Science, Geography & Religious Studies	Stairs near to S1	Stairs have light vinyl tread with black edge.
		Stairs to S7	Stairs are painted with yellow edge.
Stairs near S4		Stairs have light vinyl tread & dark edge.	
Stairs to rear of Geography Stairs near L3		Stairs are painted with yellow edge. Stairs have dark vinyl tread with blue carpet.	
Pavilion (POD)	Markings on external steps	Lines in place, need refreshing.	
Gym	Markings on external steps	Lines in place, need refreshing.	
Harland House	Markings on external steps	Lines in place, need refreshing.	

Date of audit: 3rd February 2021


Mark Parker-Randall
Special Educational Needs & Disability Coordinator



David Baldock
Chair of Governors